


Village of Glendale Heights Water



Legend

- VALVE
- VALVE VAULT
- ⊙ VALVE VAULT (NOT FOUND)
- ⊙ HYDRANT
- WATER LINES
- VILLAGE BOUNDARY
- Subdivision Built Before 1986
Copper Service Lines - Lead Solder
- Subdivision Built After 1986
Copper Service Lines - No Lead Solder



Note:
The information and depictions herein are for informational purposes and the Village of Glendale Heights specifically disclaims accuracy in this reproduction and specifically admonishes and advises any and all depictions, measurements, distances depicted herein and as to which specific or precise accuracy is required should be determined by procurement or certified maps, surveys, plats, flood insurance studies or other official means.